


Category 5 Shielded Keystone Jack Termination Instruction

Global Systems Solutions



1. Open the shielded cover.
2. Remove the appropriate amount of cable jacket. Bend the drain wire back over jacket and tighten it with the self adhesive copper strip.
3. Place wires in proper termination slots according to color chart below.
4. Use 110 punch down tool to terminate conductors.
5. Secure the cable with the cable tie to establish contact between the copper strip and the shield.
6. Snap the shielded cover into place.


Category 5 T568A (8 Wire)

Category 5 T568B (8 Wire)

110 Type RJ-45

Connector Jack

Wht/Blu	5
Blu/Wht	4
Wht/Org	3
Org/Wht	6
Wht/Grn	1
Grn/Wht	2
Wht/Brn	7
Brn/Wht	8



110 Type RJ-45

Connector Jack

Wht/Blu	5
Blu/Wht	4
Wht/Org	1
Org/Wht	2
Wht/Grn	3
Grn/Wht	6
Wht/Brn	7
Brn/Wht	8

